




### 5.7e18 POT in medium energy configuration last week.









## Protons on Target for FY10


RHC:  $1.74 \times 10^{20} \text{ POT}$ 

FHC: 1.27 x 10<sup>20</sup> POT


FY09: 3.01 x 10<sup>2</sup> POT








## Protons on Target (since 2005)







# This Week Some minders likely need to be swapped

#### **Monday**

Replaced ROP5 Swapped wiener PS for FEU2b Swapped PS chassis for FEV1b

### Tuesday


Opened DI bottle more, ran magnet at low current. Increased after resistivity increased


### Wednesday


Replaced minder causing DAQ crash RPS in FEU8 died. Swapped with FEU13

### **Thursday**

Installed new RPS in FEU8







Far Detector

No problems with far detector.